

HIBLOW®



OUTBACK 80

Built for Extreme Heat



**Field tested in the
Australian Outback**




Re-engineered diaphragms endure heat from:

- Hot outside temperature
- Enclosures that are poorly ventilated
- Elevated ATU system pressure that limits the aerator's ability to cool itself

**Often caused from fine bubble diffusers that clog and are not replaced*

Outback Rebuild Kits Available

- Retrofit standard HP-80's
- Full rebuild kits and diaphragm only kits available



Outback 80 Full Repair Kit
Item# PHPCS0011P



Outback 80 Diaphragm Only Kit
Item# PHPCS0011P